










Návod na montáž

MRX




i B




1 B


MRX 110 34




MRX 110 40




MRX 110 50





MRX 110 70




MRX 110 34-34




MRX 110 40-40




2 B








3 B




4 B













1



2



3



www.franke.com



Model

A

B

C

D

E

F

r1

r2

r3

MRX 110 34						340	400			16
MRX 110 40						400	400			16
MRX 110 50						500	400			16
MRX 110 70						700	400			16
MRX 120 34-34						705	400			16
MRX 120 40-40						825	400			16
MRX 210 34		350	410	382	442			10	11	
MRX 210 40		410	410	442	442			10	11	
MRX 210 50		510	410	542	442			10	11	
MRX 210 70		710	410	742	442			10	11	
MRX 220 34-34		715	410	743	438			10	11	
MRX 220 40-40		835	410	863	438			10	11	
MRX 210 40 TL		410	490	432	512			10	11	
MRX 210 50 TL		510	490	532	512			10	11	
MRX 210 70 TL		710	490	732	512			10	11	